




SAFETY INFORMATION

2/95

Jammed Control Line

A serious injury has occurred where a parachutist spiralled to the ground. It is a possibility that the accident may have happened due to the steering line becoming caught between the Slider Grommet and the plastic type Slider Stop preventing the parachutist from stopping the turn.

Parachutists with Slider Stops similar to the drawing below should be made aware of the possible problem.



Tony Butler
Technical Officer

24th August 1995

Distribution

CCI's
Council
Riggers
STC Mailing
Sport Parachutist
File