

BRITISH PARACHUTE ASSOCIATION  
Kimberley House  
47 Vaughan Way  
LEICESTER  
LE1 4SG

---

TO: All Clubs

S A F E T Y   N O T I C E

An incident has occurred where the Slider Stop on the Canopy of a Sky Lark Parachute, pulled through the Slider Grommet causing a rotating malfunction. On examination it was found that the material used for the Slider Stop was flexible and allowed the Stop to pull through the Slider Grommet.

This incident could re-occur. It is advised that anyone with a Sky Lark Canopy should contact a Rigger to have their Canopy checked.

For further information contact John Hitchen.

John H. Hitchen  
JOINT NATIONAL COACH &  
SAFETY OFFICER

21st June 1985