

BRITISH PARACHUTE ASSOCIATION
5 Wharf Way
Glen Parva
LEICESTER
LE2 9TF

SN 1/88

S A F E T Y N O T I C E

All T.S.E. Chaser rigs which have a metal stiffner plate in the reserve tray are grounded until a mandatory modification to the reserve ripcord housing attachment is carried out and inspected by an advanced rigger.

The drawing for the modification is being supplied to Clubs by T.S.E. and B.P.A. and will be sent out within 48 hours of this notice.

The rigger performing the modification must satisfy himself that the user of the rig is able to operate the reserve with one hand.

Tony Knight
CHAIRMAN SAFETY AND
TRAINING COMMITTEE

11th February 1988

MANDATORY MODIFICATION.

All T.S.E. Chaser rigs which have metal plates in reserve have been grounded until a mandatory mod is made to the reserve ripcord housing attachment, (see drawing below) The modification must be inspected by an advanced rigger.

Riggers performing the job must satisfy them self that the user can use the reserve with ONE hand.

(Quick loops for the reserve closure are available if required.)

A. Insure housing is tacked firmly against zero crommetts edge.

B. A Trapping tack, closing the plate cover and ripcord housing through housing cover.

39.(ii)

