

BRITISH PARACHUTE ASSOCIATION  
5 Wharf Way  
Glen Parva  
Leicester  
LE2 9TF

SN 2/88

---

S A F E T Y   N O T I C E

All T.S.E. Chasers with metal stiffners in the reserve tray are grounded until a comprehensive modification programme is carried out and inspected by T.S.E.

This modification programme is currently being drawn up by T.S.E. and will also be sent out to all Clubs and Riggers by the BPA Office once it has been accepted as suitable by the BPA.

This notice applies to ALL Chasers with metal stiffners whether or not recent modification has been carried out and supercedes Safety Notice No. 1/88.

Tony Knight  
CHAIRMAN SAFETY &  
TRAINING COMMITTEE

25th February 1988