



## SAFETY INFORMATION

4/18

### NEXT / NEXT CENTURY TANDEM

It was decided at the Riggers' Subcommittee meeting of 15<sup>th</sup> November 2018 to rescind SI 1/16. This removes the requirement for the reserve closing loop to be changed at every 100 jump inspection on the Next Tandem and Next Century Tandem harness container systems.

As per Form 112C AP(T) and Riggers are reminded that the condition of the closing loop and the seating of the reserve pilot chute still forms part of the 100-jump inspection and should be changed or tightened accordingly if required.

It is requested that any subsequent damaged loops are reported back to the Rigger's Subcommittee via F298A Equipment Related Incident Report for information.

Jeff Montgomery  
Safety & Technical Officer

Pete Sizer  
Chairman Riggers' Subcommittee

20<sup>th</sup> November 2018

Distribution:

CI's  
Council  
Riggers  
Advanced Packers Tandem  
STC Mailing  
PTO Operators  
BPA Skydive The Mag  
File