

BRITISH PARACHUTE ASSOCIATION
Kimberley House
47 Vaughan Way
LEICESTER
LE1 4SG

BRITISH PARACHUTE ASSOCIATION

SAFETY INFORMATION

It has been brought to our attention that a number of TSE Chaser assemblies manufactured in November and December 1986, and January 1987, have missed stitches on the 3 Ring confluence wrap. This is not immediately obvious because of the fabric cover.

Please ensure that this stitching is inspected prior to jumping again and if necessary, return the equipment to Thomas Sports Equipment for rectification.

For further information contact BPA (0533 519778/519635) or Thomas Sports Equipment Ltd (0262 678299).

Jacqui Wright
CHAIRPERSON RIGGERS COMMITTEE

27th April 1987