SI 7/88

SAFETY INFORMATION

A Safety Information Sheet was sent to Clubs in late 1986 referring to ripcord handles made by Dick Gays and supplied to T.S.E. advising Clubs to check these handles as the joint may be weak.

Another faulty handle has been found, therefore we would like all Clubs to check all handles supplied by T.S.E. and to check the handle strength by pull testing them across the joint.

Tony Butler

JOINT NATIONAL COACH & SAFETY

OFFICER

16th March 1988

DISTRIBUTION

Chairman STC CCI's Clubs Advanced Riggers File