


S A F E T Y   N O T I C E

Thomas Sports Equipment require all Chaser rigs which have a metal stiffner installed or were originally manufactured with a metal stiffner to be returned to them for modification according to their drawing No.: TSE 8388 (extract below). In addition, if a Chaser has a narrow ripcord housing it must have the housing firmly secured at the top of the stiffner plate, and the subsequent distance from the top of the stiffner place to the centre of the top grommet must be a minimum of 2 $\frac{1}{2}$ ".

In addition 'Rambo' type pilot chutes are not to be used on the rigs referred to in this Safety Notice, and T.S.E. will change these when doing the above modification.



Tony Knight  
CHAIRMAN SAFETY &  
TRAINING COMMITTEE

10th March 1988

Distribution: All CCI's, Clubs, Advanced Riggers