



SAFETY INFORMATION

2/91

COLLAPSIBLE PILOT-CHUTES

There has been a report in the field that a collapsible pilot-chute with shock cord squid line failed.

The shock cord broke above the stitching.

Anybody with a pilot-chute of this type of manufacture should immediately check the squid line after each jump.

David Hickling
Vice Chairman - BPA

21st January 1991