



SAFETY INFORMATION

2/05

ANTI-TWIST LOCK RISER HOUSING INSERTS

These are the metal or plastic housings inserted into some risers where you stow the excess cutaway cable.

It was noticed on a Wings container that the housing had come loose from the tape channel and was resting on the cutaway loop.

It is important to check that the housings are secure in the channel and remain clear (about 3cm) of the loop. Tack in place if necessary.

If the end of the housing is covered by the tape channel; ensure that the cutaway cable is inside the housing, and not between the housing and channel.

Tony Butler
Technical Officer
On behalf of the
Riggers Committee

19th April 2005

Distribution

CCIs
Council
Riggers
STC Mailing
Skydive – The Mag
File