



# SAFETY INFORMATION

1/08

## ‘VIGIL’ AUTOMATIC ACTIVATION DEVICES (AADs)

Following on from BPA Safety Notice 1/08 grounding VIGIL AADs manufactured prior to August 2006. At the Riggers’ Committee meeting of the 6 June 2008 it was decided that with immediate effect all VIGIL AADs must be fitted with Type 3 cutters

VIGIL units with serial numbers lower than 8000 may have either Type 1 or Type 2 cutters and these need to be replaced immediately by the manufacturer or their dealer.

The reserve packing card must be annotated to indicate that the Type 3 cutter has been fitted.

The manufacturers contact details are:

Vigil, AAD sa/nv  
Bld A.Reyers, 193  
1030 Brussels  
Belgium  
Tele: +32 2 732 65 52  
Fax: +32 2 736 06 27  
e-mail: [info@vigil.aero](mailto:info@vigil.aero)  
[www.vigil.aero](http://www.vigil.aero)

6<sup>TH</sup> June 2008

### Distribution

CCIs, Council, Riggers, STC Mailing  
Skydive – The Mag, CAA, File

Paul Applegate  
Chairman BPA Riggers’ Committee



TYPE THREE



TYPE TWO



TYPE ONE