



SAFETY NOTICE

2/09

VIGIL 'TYPE 3' CUTTERS

Following an activation of a cutter, the cutter body separated from its base. This occurred on the 19th September 2009 in Belgium.

All Vigil 'Type 3' cutters manufactured December 2007 are to be replaced prior to the next use.

Therefore any Vigil unit that has had a cutter replaced since December 2007 and the Vigil 2 listed on the attached list are grounded until the date of manufacture of the cutter has been established.

The manufacturer will replace affected cutters free of charge: www.vigil.aero - info@vigil.aero

Paul Applegate
Chairman Riggers' Sub-Committee

26th November 2009

Distribution

STC Mailing

List of Vigil II supplied with Cutter DOM: 12-07-2 (mm/yy/batch)

Quality Control Gold Hologram	Vigil Serial Number	Quality Control Gold Hologram	Vigil Serial Number
I215	7163	M277	10745
I212	7170	M278	10746
J184	7965	M279	10747
J167	8019	M281	10749
J168	8020	M282	10750
J169	8022	M283	10751
J187	8025	M284	10752
L684	9916	M285	10753
L685	9917	P613	10809
L688	9922	M446	10926
L922	10158	M462	11013
L927	10165	M473	11026
M141	10593	M474	11027
M174	10628	M489	11042
M218	10678	M604	11185
M221	10681	M629	11216
M222	10682	M737	11357
M233	10693	M767	11401
M239	10701	M783	11417
M241	10703	M956	11661
M253	10716	N020	11742
M254	10717	N050	11772
M255	10718	N061	11783
M256	10720	N084	11806
M257	10721	O973	13851
M258	10722		
M260	10724		
M261	10725		
M262	10726		
M264	10728		
M265	10729		
M267	10731		
M268	10732		
M269	10733		
M270	10734		
M271	10735		
M272	10736		
M273	10737		
M274	10739		



AAD sa/nv
 Bld A.Reyers, 193
 1030 Brussels – Belgium – Europe
 +32 2 732 65 52 – Fax : +32 2 736 06 27
www.vigil.aero - info@vigil.aero