

British Parachute Association
Kimberley House
47 Vaughan Way
LEICESTER
LE1 4SG

BRITISH PARACHUTE ASSOCIATION

S A F E T Y N O T I C E

A streaming malfunction has occurred on a G.Q. Aeroconical with a 'Thomas Sports Equipment' $\frac{1}{4}$ Bag/Diaper deployment system. This type of $\frac{1}{4}$ Bag/Diaper will need a modification to the 'mouth-lock' and is grounded until such modification is carried out.

Contact: Thomas Sports Equipment
Top Floor
102-104 St. John Street
Bridlington
North Humberside

Tele: (0262) 78299

The modification will be completed immediately, free of charge.

Tony Butler
Joint National Coach & Safety
Officer

15th February 1984

Distribution

Chairman BPA
Chairman STC
CCI's
Clubs
Advanced Riggers
File