

BRITISH PARACHUTE ASSOCIATION
5 Wharf Way
Glen Parva
LEICESTER
LE2 9TF

S A F E T Y N O T I C E

It has been brought to the BPA's attention that a number of Ripcord Handles (mains and reserve) supplied to Thomas Sports Equipment by Dick Gays have failed.

Any ripcords purchased (separately or with containers) from T.S.E. since September 1986 with No. L8610, L8611 or L8612 must not be used, and should be returned for replacement to: T.S.E. 102-104 St. John Street, Bridlington, North Humberside (Tel:- 0262 678299)

7th February 1986

Distribution

Chairman STC
All CCI's
Advanced Riggers
Thomas Sports Equipment
Dick Gays
Council
D. Waterman