



SAFETY INFORMATION

4/90
b

BROMOCREOSOL TESTING

Bromocreosol may not give accurate indications of acid levels in nylon if it has been exposed to air too frequently, or has been in use for a lengthy period of time. Therefore, it is recommended that Bromocreosol is replaced at fairly frequent intervals.

It is also recommended that netted round reserve canopies are Bromocreosol tested at every re-pack [testing may only be carried out by an Instructor or Rigger], as it has been found that a number of reserves that had previously passed the Bromocreosol test, subsequently failed a further test.

Tony Butler
National Coach & Safety Officer

20th July 1990.

Bromocreosol Green P.H. Testing Solution may be obtained from:-

Kim Newton,
Doncaster Parachute Centre.
Tel. [0302] 532922.

Distribution

All CCI's
Clubs
All Advanced Riggers